



SI B 24 10 00  
Automatic Transmission

October 2000  
Service Engineering

## Advance Information

This bulletin is also issued in Group 12 (Engine Electrical), SI 12 11 00, the contents of which are identical.

### SUBJECT

**MS43 DME Removal Precautions – EGS Failure Avoidance**

### MODEL

All with MS43 control unit

### SITUATION

The MS43 control module may stay "alive" after the key is off, due to the DM-TL test.

If the following procedure is not followed, irreparable damage to the EGS control module will occur.

### PROCEDURE

1. Always verify that the ignition key is in the "off" position before disconnecting the DME.
2. Allow, at least, **3 minutes to elapse**, after the key was set to the "OFF" position before disconnecting the DME. This will allow for sufficient time to complete the DM-TL test.

### WARRANTY INFORMATION

For information only

[ Copyright © 2000 BMW of North America, LLC ]

**080100**