



SIB 63 51 00  
Lights

December 2000  
Service Engineering

---

**SUBJECT**

**Shifter LED Stays Illuminated**

**MODEL**

X5 (E53) with Automatic Transmission

**SITUATION**

On some X5 vehicles, the shifter console LED stays illuminated after consumer shut off.

**CORRECTION**

**Do not replace any parts, this is a normal situation and will not result in a discharged battery.**

If a customer complains of a low battery, check closed circuit current (SIB 61 08 00 dated 08/00) and troubleshoot the vehicle electrical system in the regular way.

**WARRANTY INFORMATION**

Information only

[ Copyright © 2000 BMW of North America, LLC ]

**080126**